NCRTD Executive Board of Directors Meeting
Taos Operations & Maintenance Facility
Construction Update

January 5, 2024





RidetheBlueBus.com 505-629-4725 866-206-0754



















Masonry stem walls looking southeast



Concrete wall at north patio area





Plumbing and electrical rough-in



Plumbing and electrical rough-in





Secondary power conduit trench looking north



North retaining wall footing and rebar





Fueling station island concrete protective sheets



Charging station canopy imbeds





Concrete forms at generator island









Secondary power at Salazar

Concrete drainage pipe









Thank you! Questions?

Blue RTD

RidetheBlueBus.com 505-629-4725 866-206-0754