

Taos Operations & Maintenance Facility Construction Update

NCRTD Executive Board of Directors Meeting
February 2, 2024

Blue
bus

NORTH
CENTRAL
RTD

RidetheBlueBus.com
505-629-4725
866-206-0754



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Video Clip – click to play



Construction Highlights

Protective blankets, stem walls, rebar



Stem walls, conduit, plumbing



Construction Highlights

Plumbing penetration at stem wall



Cinder block stem wall with rebar and conduit



Construction Highlights

Underground plumbing and trench



Plumbing and trench





Thank you!
Questions?

RidetheBlueBus.com
505-629-4725
866-206-0754